

**SGS ITALIA S.p.A.**  
**ORGANISMO NOTIFICATO N. 1381**

Industrial  
 Via Caldera, 21  
 20153 Milano  
 Tel. (02) 7393.1 Fax: (02) 70125057  
 Affilia code 095103

Id. : CER.CPR. Strutture acciaio e Alluminio  
 Rev. 1  
 Page 1 of 1

FILE N. 18.14641

## Certificate of Conformity of the Factory Production Control

**1381-CPR-588**

**Venice, 09 September 2019**

In compliance with Regulation 305/2011/EU of the European Parliament and of the Council of 9 March 2011 (the Construction Product Regulation or CPR), this certificate applies to the construction product

### Structural Steel and Aluminum Components

Produced by:

Manufacturer:	<b>Tianjin Wellmade Scaffold Co., Ltd</b>
Address:	<b>No.1 Guangyuan Road, Tangguantun Industrial Logistic Zone, Jinghai, Tianjin, China</b>
Authorised representative:	<b>Zhou Xin Compagnie Industrielle Internationale S.A.</b>
Address:	<b>281, Route d'Arion, L-8011 STRASSEN, Luxembourg</b>

This certificate attests that all provisions concerning the assessment and verification of constancy of performance and the performances described in Annex ZA of the standards

**EN 1090-1:2009+A1:2011**

**Execution of Structural Steel Components**  
**Execution class up to EXC2**  
**Methods of Declaration: 3a**

Are applied according to Sistem 2+ and that the product and the Factory Production Control fulfils all the prescribed requirements.

This certificate has been issued on **09 September 2019** and will remain valid as long as the harmonized standard remains valid or the manufacturing conditions in the plant or the factory production control itself are not modified significantly.

This certificate is a translation of the original certificate nr. 1381-CPR-588 in Italian language and must not be used for any legal interpretation.

Date of last issue: **09 September 2019**

The Authorized Representative  
 p.p. Marco De Maria

The Technical Director  
 Flaviano Proserpi-Flaviani

Member of SGS (Société Générale de Surveillance) Group



Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. The SGS stamp and signature merely represents receipt of the document and SGS makes no representations as to the accuracy, adequacy and/or completeness of third party or laboratory results, reports or certifications. Any holder of this document is advised that the information contained herein is limited to visual examination of the readily accessible portions of the consignment only. Safety for services related to witnessing/observing a third party's intervention(s) in accordance with Client's instruction, the Company's involvement has been limited to witnessing/observing a third party's intervention(s) at the third party's laborator/test house or other facilities and installations used for the intervention(s). The Company's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, skills or competence of the third party's personnel or the analysis results.

Member of the International Federation of Inspection Agencies Limited, London.